BURNDY POOL WATER BONDING KITS						REV	DATE		RIPTION	ECO E	Y C'H'K.
CATALOG	ITEM	"UPC"				C	07/14/2020	SHOWN	AND BWB680IG DETAILS	53863 F	B RG
APPLICATION NUMBER	NUMBER	CODE									
IN GROUND BWB680IG	10110593	78181049868									
ABOVE GROUND BWB680AG	10110592	78181049867			INSULATE	D VIEW					
INCLUDED IN KIT : ONE BONDING PLATE (STAINLESS STEEL), ONE RUBBER SEALING WASHER, TWO FLAT WASHERS, TWO LOCK WASHERS, TWO NUTS AND ONE BURNDY "CL50ITN" IMPORTANT SAFETY INSTRUCTIONS: THE INTEGRITY OF THE BONDED CONNECTION SHOULD BE PERIODICALLY INSPECTED.						CUTAWAY VIEW					
				BONDING PLATE (STAINLESS STEEL) BURNDY CL501TN (INCLUDED)				BONDING PLATE (STAINLESS STEEL) RUBBER WASHER		BURNDY CL50 (INCLUDED)	1TN
INSTRUCTIONS FOR INSTA	ALLATION:			$\land$							
1. FIRST, DRILL A 3/16 INCH HOLE THE SKIMMER BASKET IS HELD. BOTTOM OF SKIMMER CASING A OF THE SKIMMER FOR THE BON	LOCATE THE BO	ONDING PLATE AS	CLOSE TO THE					NDY CL501TN			
2. PLACE THE RUBBER WASHER ON BONDING PLATE.	N THE BASE OF T	THE THREADED STU	JD ON THE	F	BWB680AG ORIZONTAL PLATE	BWB680	$\bigcirc$	CLUDED)			
3. PUSH THREADED STUD THROUG	GH THE 3/16 INC	H HOLE PREVIOUS	LY DRILLED.			VERTICAL I					
4. SECURE WITH A FLAT WASHER, "CAUTION: DO NOT OVER TIGH		AND NUT IN THAT	ORDER.					BURNDY® PRODUCTS CALL	POOL WATER E	SONDING KITS	
5. USE THE REMAINING FLAT WAS	HER AND NUT T	O SECURE THE BOI	IDING LUG.				ا 1-800-346-4	JNITED STATES 175 (LONDONDERRY, NH)	CAT. NO:SEE TABLE DRAWN BY: A.MONTMINY 06/09 CHECKER: P.THERRIEN DSN APRVL: A.MONTMINY 06/10		
6. LAST, CONNECT SOLID COPPER BONDING LUG. THE COPPER WI METAL PARTS OF THE SWIMMIN THE SWIMMING POOL.	RE SHOULD ALS	O CONNECT TO MO	TOR AND ALL				1-800-387-648	CANADA: -361-6975 (QUEBEC) 87 (ALL OTHER PROVINCES) T INFO: http://www.burndy.com	DSN APRVL: A.MONTMINY 06/10 MFG APRVL:	DRAWING	G NO REV 073 C